

N^o 11268

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-8-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

232'

HOUSE NO. 2369

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? Y/N S

WAS ATTACHED TO MAIN Y/N S

NAME OF CONTRACTOR

Malamito Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill [Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11268

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/8, 2058

RECEIVED OF McQuate FEE OF \$ 58

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP Sanitary SEWER ON THE South SIDE
CUTOFF Milburn Hall Ave.

OF Milburn Hall Ave. ST. TYPE OF STREET Asph. Pav.

THE PREMISES BEING LOT NO. 116081, HOUSE NO. 2369

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR James H. Halling

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.