


Nº 11276

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 6/13/01 IF SO, HOW AND LOCATION FROM 130'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1340
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11276

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/29

RECEIVED OF

Springhill Condo at 1134

FEE OF \$

50

FOR WHICH PERMISSION IS GRANTED

Grubice

REPAIR

TO TAP

CUTOFF

Sanitary

SEWER ON THE

North

SI

OF

Laurelbrook Dr

AVE

ST. TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO.

02857

, HOUSE NO.

1340

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Springhill Condo

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.