Nº 11279

REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	6/13/01	IF SO, HOW AND LOCATION FROM	116'
HOUSE NO	1355	FIRST MANHOLE DOWN STREAM	118
SIZE OF PIPE USED	6 *	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	yes	— NAME OF CONTRACTOR	Grabill
SHOW BY DIAGRAM RELATION	of Lateral to Wall o	F BUILDING SERVED. 116' 8"	C/Q C/Q Laurenbrook Lane
	Inspector for City		

Nº 11279

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		/
	MAȘSILLON, OHIO,	<u> 5/17,</u> 20_
RECEIVED OF Jakuafull	Cordo Ck 1/3	EFOF\$ 5
FOR WHICH PERMISSION IS GRANTED	Gurliel	
TO TAP AMALUN SEWE	R ON THE MONTHS	th
	OF STREET AND	Mult
THE PREMISES BEING LOT NO.	/, HOUSE NO	/353
WORK TO BE DONE IN ACCORDANCE META ODDINANCE NO. 40 4	OTA DULY DARRED BY THE CITY COUNCIL	AND DUI SO OF THE
f.	971 DDLY PASSED BY THE CITY COUNCIL	L, AND HULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	$\sim \Omega$	V
NAME OF CONTRACTOR LAULANI	Cordo	
	THE PREMISES BEING LOT NO.	RECEIVED OF STREET TO TAP SEWER ON THE ST. TYPE OF STREET THE PREMISES BEING LOT NO. WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.