## Nº 11281

REMARKS \_\_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	6/13/01	IF SO, HOW AND LOCATION FROM 310'			
HOUSE NO.	1365	FIRST MANHOLE DOWN STREAM			
SIZE OF PIPE USED	6*	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT			
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH			
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR			
SHOW BY DIAGRAM RELATION	OF LATERAL TO WALL C				
	Θ	8" c/o is located 3' = of ne corner  8" c/o,  Laurenbrook Lane			
SIGNED	Inspector for City FILED AT ENGINEER'S OFFICE				
	mapector for Oity				

## Nº 11281

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO, _	5/29	20
RECEIVED OF Advisage	ill Cordo	CR / FEEGES	څ
FOR WHICH PERMISSION IS GRANTED	Grabell		
TO TAP Sanitary	SEWER ON THE	South	!
OF Julen brook Tas	VE., TYTYRÉ OF STREET	andret	
THE PREMISES BEING LOT NO.	857, House	ENO	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE I	/ NO. 19.1971 DULY PASSED BY	THE CITY COUNCIL, AND RULES OF	THE
DEPARTMENT OF PUBLIC SERVICE.	<i>, A</i>		
NAME OF CONTRACTOR	ul oul		•

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.