


N^o 11282

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/13/01 IF SO, HOW AND LOCATION FROM 295'
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 1370
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



295'
8"
SIGNED *J. H. m. K. J.* Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11282

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/29 2010

RECEIVED OF Springhill Condo Ct 1136

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Garbriel

REPAIR
TO TAP
CUTOFF

SEWER ON THE North SI

OF Laurentbrook Dr

AVENUE
ST. TYPE OF STREET dr. p. h. t.

THE PREMISES BEING LOT NO. 00857

, HOUSE NO. 1370

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Springhill Condo

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.