


Nº 11285

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6/13/01 IF SO, HOW AND LOCATION FROM 310'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1385
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11285

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/29
20
RECEIVED OF Springfield Condo Assoc FEE OF \$ 50
FOR WHICH PERMISSION IS GRANTED Garfield
REPAIR
TO TAP Sanitary SEWER ON THE South S
CUTOFF
OF Laurelhurst Dr AVE. 176
ST. TYPE OF STREET depressed
THE PREMISES BEING LOT NO. DC 857, HOUSE NO. 1385

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Springfield Condo

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**