


Nº 11286

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED	6/13/01	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	295'
HOUSE NO.	1390	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
SIZE OF PIPE USED	6"		
WAS LATERAL AT CURB?	yes		
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



295'
8"

C/D 11' W OF NE CORNER

SIGNED *[Signature]* Inspector for City FILED AT ENGINEER'S OFFICE

REMARKS _____

Nº 11286

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/24, 20

RECEIVED OF Springhill Condo OK 1/31 FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Grubel

REPAIR TO TAP Sanitary SEWER ON THE North SIDE
CUTOFF Laurelwood Dr

OF Laurelwood Dr AVE. 16
ST. TYPE OF STREET Resident

THE PREMISES BEING LOT NO. 04857, HOUSE NO. 1390

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Springhill Condo

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.