

Nº 11288

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5/8/01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

144'

HOUSE NO. 1420

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Jeffrey M. King

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11288

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/29/90
RECEIVED OF Springhill Condo CK 1136 FEE OF \$ 57

FOR WHICH PERMISSION IS GRANTED Shubert

REPAIR TO TAP Sp Sanitary SEWER ON THE North SIDE
CUTOFF

OF Lawrencewood Dr AVE. ST./TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 02857, HOUSE NO. 1420

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Springhill Condo

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.