


N^o 11292

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5/8/01 IF SO, HOW AND LOCATION FROM 144'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1440
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11292

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/29
RECEIVED OF Springhill Condo 1136 FEE OF \$ 50
FOR WHICH PERMISSION IS GRANTED Sanitary
REPAIR TO TAP Sanitary SEWER ON THE North SIDE
CUTOFF Laurelbrook AVE. West ST. TYPE OF STREET West
OF Laurelbrook ST. TYPE OF STREET West
THE PREMISES BEING LOT NO. 01 857, HOUSE NO. 1440

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Springhill Condo

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.