

Nº 11296

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-1-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 4563-4565

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR J. H. Little

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED B. C. P.

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11296

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

5/24/01

RECEIVED OF _____

FEE OF \$ _____

5

FOR WHICH PERMISSION IS GRANTED _____

Jacob Glick

REPAIR
TO TAP
CUTOFF

tap sanitary

SEWER ON THE _____

South

SI

OF _____

~~Lincoln St~~

N/A

AVE.

ST. TYPE OF STREET _____

asphalt

Evangel Ave

THE PREMISES BEING LOT NO. _____

(29)

16146

, HOUSE NO. _____

4563/4565

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Jacob Glick

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.