Nº 11298

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-/4-0/	IF SO, HOW AND LOCATION FROM 150 FIRST MANHOLE DOWN STREAM
HOUSE NO. 2355	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 49 5	
WAS ATTACHED TO MAIN 425	NAME OF CONTRACTOR Malante Echo
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BU	JILDING SERVED.
	18/21° 8/DEF)
SIGNED_BireCarrier	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	

Nº 11298

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

	MAS	SILLON, OHIO,	6/1220
RECEIVED OF	Malaute		FEE OF \$
FOR WHICH PERMISSION IS GRANTE	D		
TO TAP	SEWER ON	THE	Loutek.
of All Crail	AVE. ST TYPE OF S	TREET	and the 1 for
	16082		1359
THE PREMISES BEING LOT NO		######################################	
WORK TO BE DONE IN ACCORDANCE	E WITH OFDINANCE NO. 19.1971 D	ULY PASSED BY THE CIT	Y COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	-1		
NAME OF CONTRACTOR	Horalo lago	Usalley	_
		0	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.