## Nº 11308

REMARKS \_\_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 742.6/	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 1020-1022	FINGT MANNOCE DOWN STREAM		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? 45 5			
WAS ATTACHED TO MAIN 7/17 5	NAME OF CONTRACTOR M. Junily Eps.		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BO	JILDING SERVED.		
	6'DEEP		
SIGNED Bus Parinces	1 DER		
Inspector for City	FILED AT ENGINEERS OFFICE		

## Nº 11308

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON	ı, ohio,	July 5, 20	(-2 <sub>0</sub>
RECEIVED OF			FEE OF \$	<u> </u>
FOR WHICH PERMISSION IS GRANTED	Majavite	Freuvo	tra	
REPAIR TO TAP	SEWER ON THE		Fret	;
of Alma Strain	AVE. ST. TYPE OF STREET		a rate 1+	<del> </del>
THE PREMISES BEING LOT NO.	16151	, HOUSE NO	4	LE(
WORK TO BE DONE IN ACCORDANCE WITH ORDIN	IANCE NO. 19.1971 DULY PA	SSED BY THE CIT	Y COUNCIL, AND RULES OF	THE
DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR	lavite :		_	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.