## Nº 11316

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-5.0/ HOUSE NO. 1245	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Stone Eje.	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	2-45 8 15' IT IT IS SET Y AT MAST	
SIGNED A SIGNED / Inspector for City	FILED AT ENGINEER'S OFFICE	
DEMARKS		

Nº 11316

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	7/9,20
RECEIVED OF Wilder	a Hone	FEE OF \$
FOR WHICH PERMISSION IS GRANTED		
REPAIR TO TAP	SEWER ON THE	tarini .
CUTOFF OF	AVE.	Bridge Bridge Bridge
THE PREMISES BEING LOT NO.	/ - 9-0 / HOUSE NO	1445
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCI	E NO. 19.1971 DULY PASSED BY THE CIT	Y COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	$\mathcal{J}_{i}$	
NAME OF CONTRACTOR	11tral	_

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.