FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	8/16/01	IF SO, HOW AND LOCATION FROM 126'		
HOUSE NO.	1015			
SIZE OF PIPE USED	6*	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?	yes			
WAS ATTACHED TO MAIN	yes	Grabill NAME OF CONTRACTOR		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
Scottwood Place A' Fron S corner 1015 B'				
SIGNED		FILED AT ENGINEER'S OFFICE JUMP M King		
	Inspector for City	77.7		
	•	,		

Nº 11317

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

/	MASSILLON, OHIO,	
RECEIVED OF Altertification	Couls FEE	of \$ 50
FOR WHICH PERMISSION IS GRANTED	aliel	
TO TAP SEWI	ER ON THE ULCE	<i>±</i>
OF Sadword PC TOP	E OF STREET USE	hult
THE PREMISES BEING LOT NO	7, HOUSE NO	1015
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19. DEPARTMENT OF PUBLIC SERVICE.	1971 DULY PASSED BY THE CITY COUNCIL, AI	ND RULES OF THE
NAME OF CONTRACTOR About 1		
Note: This permit covers work out	tside of huilding only. Any s	work inside

walls of building is subject to Massillon Board of Health regulations.