Nº 11318

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	8/16/01	_ IF SO, HOW AND LOCATION FROM 126'						
HOUSE NO.	1025	FIRST MANHOLE DOWN STREAM						
SIZE OF PIPE USED	6*	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT						
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH						
WAS ATTACHED TO MAIN	yes	Grabill						
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.								
Scottwood Place 4' From S corner								
	h.	8"						
SIGNED JAMEN A	Inspector for City	FILED AT ENGINEER'S OFFICE						

Nº 11318

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	/	MASSIL	LON, OHIO,		7/, 20/2
RECEIVED OF	Letu	ghill	Cordo	FEE OF \$	50
FOR WHICH PERMISSION IS GRANT	ED	Gustu	ce	·	
TO TAP CUTOFFF	Huy	SEWER ON TH		west	
of Sactury	al PX X	AVE. ST. TYPE OF STRI	EET	aspla	0+
THE PREMISES BEING LOT NO	01	587	, HOUSE NO		7.
WORK TO BE DONE IN ACCORDANC DEPARTMENT OF PUBLIC SERVICE.	E WITH ORDINANC	E NO. 19.1971 DUL	Y PASSED BY THE CI	TY COUNCIL, AND RI	ÚLES OF THE
NAME OF CONTRACTOR	quely	el		inner	

Note: This permit covers work outside of building only. Any work inside

walls of building is subject to Massillon Board of Health regulations.