


N<sup>o</sup> 11320

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED 8/16/01 IF SO, HOW AND LOCATION FROM 126'  
FIRST MANHOLE DOWN STREAM  
HOUSE NO. 1045  
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_  
WAS LATERAL AT CURB? yes  
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill  
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



126'  
8"

SIGNED [Signature] Inspector for City FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS \_\_\_\_\_

N<sup>o</sup> 11320

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, 7/11/20

RECEIVED OF

Springhill Condo (ck 1707) 50  
FEE OF \$

FOR WHICH PERMISSION IS GRANTED

Graham

REPAIR  
TO TAP  
CUTOFF

Sanitary

SEWER ON THE

West SI

OF

Scotwood Pl

AVE

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

06587

, HOUSE NO.

1045

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Graham

**Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.**