


N^o 11322

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8/16/01 IF SO, HOW AND LOCATION FROM 129'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1065
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Jeffrey M. King

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 11322

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/16/65
RECEIVED OF Springhill Condo (Ch 120) 50
FOR WHICH PERMISSION IS GRANTED Guarini
REPAIR TO TAP Sanctuary SEWER ON THE West SIDE
CUTOFF Scotwood Pl AVE. ST. TYPE OF STREET asphalt
OF 06587 THE PREMISES BEING LOT NO. 1065, HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Guarini

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.