

Nº 11326

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-19-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 2370

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Malomite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Bio R. Jones
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

N^o 11326

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/17, 20

RECEIVED OF Malawite

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP Sanitary SEWER ON THE North SIDE
CUTOFF Malone Ave AVE.
OF Malone Ave ST. TYPE OF STREET asphalt
THE PREMISES BEING LOT NO. 16084, HOUSE NO. 2370

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Homes by Ashley

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.