


Nº 11331

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-26-01 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 263
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Malomitic Epc.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Repair

Nº 11331

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 7-26, 20 0

RECEIVED OF Miracle Plumbing FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP CUTOFF Sewer SEWER ON THE Wet ST. OF Arthur St S AVE. ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 12337, HOUSE NO. 263

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Miracle Plumbing

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.