


Nº 11337

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-6-01 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 2846
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR J. Slick
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

NY



SIGNED Bill P... FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11337

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/2, 20
RECEIVED OF J. Gluck FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

REPAIR TO TAP Sanitary SEWER ON THE North SIDE
CUTOFF See On Map AVE.
OF See On Map ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 15815, HOUSE NO. 2846

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR J. Gluck

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.