


Nº 11346

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-6-01 IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 2265
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? YES
WAS ATTACHED TO MAIN YES NAME OF CONTRACTOR Malcolm Egan
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11346

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, SEPT 6, 2050

RECEIVED OF MALAVITE EXCAVATING INC. FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED MALAVITE EXCAVATING INC.

REPAIR
TO TAP SANITARY SEWER ON THE WEST SIDE
CUTOFF

OF UNIVERSITY DR. SE ST. TYPE OF STREET ASPHALT

THE PREMISES BEING LOT NO. 15779, HOUSE NO. 2265

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR MALAVITE EXCAVATING INC.

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**