REMARKS ___

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-20-01 HOUSE NO. 238.5	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 755 WAS ATTACHED TO MAIN 755	NAME OF CONTRACTOR Siss & Gle,
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED.
SIGNED Bill Com	20 13' A 13' FILED AT ENGINEER'S OFFICE
Inspector for City	

Nº 11350

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON,	OHIO,	1,207
FOR WHICH PERMISSION IS GRANTED			
REPAIR TO TAP CUTOFF	SEWER ON THE	South	
OF Phille Med	ST_TYPEFOF STREET_	agrant	
THE PREMISES BEING LOT NO.	12562-	, HOUSE NO	
WORK TO BE DONE IN ACCORDANCE WITH C	ORDINANCE NO. 19.1971 DULY PASS	SED BY THE CITY COUNCIL, AND RULES O	FTHE
NAME OF CONTRACTOR	Eddening		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.