## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	9/26/01	IF SO, HOW AND LOCATION FROM 91'							
HOUSE NO.	4360	FIRST MANHOLE DOWN STREAM							
SIZE OF PIPE USED	6*	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT							
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH							
WAS ATTACHED TO MAIN	yes	Palmer & son Exc. NAME OF CONTRACTOR							
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.									
4360 Sterillte se 39' 45' 39' 45' PB'35' reducer  SIGNED MAM MA  FILED AT ENGINEER'S OFFICE									
77/	Inspector for City								
REMARKS									

Nº 11354

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	. <b>\</b>		HIO,		<u></u>
RECEIVED OF	Interma	framal End	Eryphices 6	FEE OF \$	<u> Paring</u>
FOR WHICH PERMISSION IS GRANTED	)	·····			
REPAIR TO TAP	<u> </u>	SEWER ON THE	<u> </u>	<u>+</u>	s
сито <del>гг</del> ог <u>5 2 1 д з</u>	S-E- S	VE, T. TYPE OF STREET	<u> </u>	-1, 14	
THE PREMISES BEING LOT NO	0.4.	753	HOUSE ÑO	- 77473	60
WORK TO BE DONE IN ACCORDANCE DEPARTMENT OF PUBLIC SERVICE.	WITH ORDINANCE N	NO. 19.1971 DULY PASSE	ED BY THE CITY CO	UNCIL, AND RULE	S OF THE
NAME OF CONTRACTOR	Poloner	1 Som		I Land	٠.

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.