## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	10/03/01	IF SO, HOW AND LOCATION FROM 1119"					
HOUSE NO.	/327	FIRST MANHOLE DOWN STREAM					
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT					
WAS LATERAL AT CURB?	yyess	CURB LINE AND DEPTH					
WAS ATTACHED TO MAIN	y/ess	Gratbill NAME OF CONTRACTOR					
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED 118							
		B Irom w corner					
		Tylers Mill Lane  /327  Sign					
SIGNED M M	Inspector for City	FILED AT ENGINEER'S OFFICE					
REMARKS							

## $N^{\circ}$ 11357

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

				1
$A_{ij}$	B	MASSILLON,	. OHIO. ————	9/28
RECEIVED OF	Sphinghe	el Con	do chi	-FEEDF\$
OR WHICH PERMISSION IS GRA	ANTED		•	
O TAP CUTOFF A CLU		EWER ON THE	(30)	The Whole to
HE PREMISES BÉING LOT NO.	PFOL	XJ /	_, HOUSE NO	1327
•		,		/
VORK TO BE DONE IN ACCORD. DEPARTMENT OF PUBLIC SERVI		19.1971 DULY PAS	SED BY THE CITY COUN	CIL, AND RULES OF THE
CHANNER OF TOBERO BERN	<u>^</u>	0		
IAME OF CONTRACTOR	Mulu		<u> </u>	
N.T				

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.