


N^o 11364

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10/03/01 IF SO, HOW AND LOCATION FROM 312'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1397
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Grabill

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11364

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/28

RECEIVED OF

Springhill Cddo #1293

FEE OF \$

150

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

Sanitary SEWER ON THE South SIDE
OF Tyler Mill Rd AVE. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO.

PT 01 857

HOUSE NO.

1297

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Guabill

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.