Nº 11369

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1805	DISTANCE FROM FIRST MANHOLE
WAS LATERAL AT CURB?	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN 45	NAME OF CONTRACTOR Jenny & Cho.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BL	
	6'1989
\mathcal{N}^{\perp}	10' ABS
· · · · · · · · · · · · · · · · · · ·	26'
SIGNED_Birton	22° 7 PAR
Inspector for City	TIEDAI ENGINEETI OOTTIGE

Nº 11369

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	\wedge	MASSILLON	, OHIO,	10	1/208
RECEIVED OF	John	is Ex Car	atus	FEE OF \$	<u> 57</u>
FOR WHICH PERMISSION IS G	RANTED		U_{\perp}		
TO TAP CUTOEE	and help	SEWER ON THE	·	-	
OF Marie	ofly st	AVE. ST. TYPE OF STREET	- Uy	and a lite	
THE PREMISES BEING LOT NO)	056	_, HOUSE NO	1805	
	,		•	•	
WORK TO BE DONE IN ACCOR	DANCE WITH ORDINANC	E NO. 19.1971 DULY PAS	SED BY THE CITY CO	UNCIL, AND RULES O	FTHE
DEPARTMENT OF PUBLIC SER	VICE.	and the same	**		
NAME OF CONTRACTOR	Jehr	15 CXCu	why		
	$\mathcal{T} = \mathcal{T}$	<i>f.</i>	0	4.	

Note: This permit/covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.