## $N^{0}$ 11383

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 16-22-61	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR 1 Cothet Considered		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	5'PREP LE Y		
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE		
REMARKS			

Nº 11383

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	10/22,20
RECEIVED OF	Cothell	FEE OF \$
FOR WHICH PERMISSION IS GRANTE	D	
REPAIR TO TAP	Mi Allusewer on the	Maria.
OF	AVE ST. TYPE OF STREET	anhalt
THE PREMISES BEING LOT NO.		0
WORK TO BE DONE IN ACCORDANCE	WITH ORDINANCE NO. 19.1971 DULY PASSED BY TH	E CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	A	
NAME OF CONTRACTOR	Catchiel	· .

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.