## Nº 11387

REMARKS \_\_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-30-0	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO. 2-3-9-70	DISTANCE FROM FIRST MANHOLE			
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT			
WAS LATERAL AT CURB? 455	CURB LINE AND DEPTH			
	NAME OF CONTRACTOR Malumita Education			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
:	5 ABS 1-108 MJ			
SIGNED Conspector for City	10 DF F F FILED AT ENGINEER'S OFFICE			

## Nº 11387

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON,	OHIO,		<b>%</b> = 3
RECEIVED OF	Mulauite	· · · · · · · · · · · · · · · · · · ·	FEE OF \$	<u>57</u>
FOR WHICH PERMISSION IS GRANTED	Management .		<del> </del>	
TO TAP CUTOFF WILLIAM	SEWER ON THE	<u>N 4-0</u> G	eddald eddald	5
THE PREMISES BEING LOT NO.	,			,
WORK TO BE DONE IN ACCORDANCE VIDENATION OF PUBLIC SERVICE.	WITH ORDINANCE NO. 19.1971 DULY PAS	SED BY THE CITY O	OUNCIL, AND RULES OF	THE
NAME OF CONTRACTOR	Smith Hon	10		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.