

N^o 11388

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-30-01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 420

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Lisa C. Co.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Rogers
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

N^o 11388

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, October 30, 20 01

RECEIVED OF _____ FEE OF \$ \$50.00

FOR WHICH PERMISSION IS GRANTED Tissot Excavating

REPAIR TO TAP tap sanitary SEWER ON THE East SIDE
CUTOFF

OF Joshua Street NW AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16108, HOUSE NO. 420

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Tissot

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.