

Nº 11389

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

LARRY
339 705-058

DATE INSPECTED _____ IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. _____
SIZE OF PIPE USED _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? _____
WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

No Cut of Inspection

SIGNED _____ FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11389

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/1/06
RECEIVED OF Ernst Ludwig FEE OF \$ 11

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP _____ SEWER ON THE _____ S
CUTOFF _____
OF Cherry Rd AVE. North
ST. TYPE OF STREET Asphalt
THE PREMISES BEING LOT NO. 2306, HOUSE NO. 67

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ernst Ludwig

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**