## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	11/19/01	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
HOUSE NO.	4570-72		
SIZE OF PIPE USED	6"		
. WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTORJohns Excavating	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	$\bigwedge^{\uparrow}$	4570   6'do   4572   36'   -5'-	
		294'	
SIGNED Jeff In	Inspector for City	8"  FILED AT ENGINEER'S OFFICE	

## $N^{0}$ 11393

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICI PERMIT TO TAP SEWER

A MASSIL	LON, OHIO,//, 20 9
RECEIVED OF HAND CACA	FEE OF \$ 5
FOR WHICH PERMISSION IS GRANTED	<u> </u>
TO TAP SEWER ON THE	E Maletha
CUTOFF-7 /	ET Wapt 1 till
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY DEPARTMENT OF PUBLIC SERVICE.	/ PASSED BY THE CITY COUNCIL, AND RULES OF THE
NAME OF CONTRACTOR WWW. Justy	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.