

Nº 11395

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____ IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. _____
SIZE OF PIPE USED _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? _____
WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Void see permit # 11401

SIGNED _____ FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11395

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/13/01, 20

RECEIVED OF Malavite FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Malavite Excavating

REPAIR TO TAP CUTOFF tap sanitary SEWER ON THE 1st St SI

OF Championship Circle S^{AVE.} ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16194, HOUSE NO. 2446

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.