

Nº 11396

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11/19/01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

84'

HOUSE NO. 2380

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED *[Signature]*
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11396

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/13/01, 2001

RECEIVED OF _____ FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED Malavite Excavating Malavite

REPAIR TO TAP top sanitary SEWER ON THE North SIDE
CUTOFF

OF Malone Ave SE AVE. ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16085 (162), HOUSE NO. 2380

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.