Nº 11403

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	12/6/01	_ IF SO, HOW AND LOCATION FROM	93'		
HOUSE NO.	741	FIRST MANHOLE DOWN STREAM	33		
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT			
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH			
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Robert Schear		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.					
		741 3rd st NW	<u> </u>		
			-123'		
			22° & 45° @ main		
SIGNED Bill Papp	Inspector for City	FILED AT ENGINEER'S OFF	FICE		
	inspector for Ony				

Nº 11403

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	7/ MASSILLON, C	DHIO,	ر المرادي /
RECEIVED OF	Halderbruen		FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Masai	Close 1	Lilvage
REPAIR TO TAP	SEWER ON THE		1224
OF	AVE. ST. TYPE OF STREET		Paradas de La Companya de la Company
THE PREMISES BEING LOT NO	Al Com	HOUSE NO.	1947
WORK TO BE DONE IN ACCORDANCE WIT DEPARTMENT OF PUBLIC SERVICE.	TH ORDINANCE NO. 19,1971 DULY PASSI	ED BY THE CITY CO	DUNCIL, AND RULES OF THE
NAME OF CONTRACTOR	Loldenbaum		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.