Nº 11404

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED | 12/4/01 | IF SO, HOW AND LOCATION FROM 120' | | | | |
|---|----------------------|--|--|--|--|--|
| HOUSE NO. | 2228 | | | | | |
| SIZE OF PIPE USED | 6" | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT | | | | |
| WAS LATERAL AT CURB? | yes | CURB LINE AND DEPTH | | | | |
| WAS ATTACHED TO MAIN | yes | NAME OF CONTRACTORTripile Diamond | | | | |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. | | | | | | |
| | | 2228 Duone NW 13' 45' 26' 21-45' | | | | |
| SIGNED W | (Inspector for City | 13'dp FILED AT ENGINEER'S OFFICE | | | | |

Nº 11404

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | // MASSILLOI | N, OHIO, | /4/3, 20_ | |
|---------------------------------|---|----------------|---------------------------------------|-----|
| RECEIVED OF | Mysle lla | inou d | FEE OF \$S | 7 |
| FOR WHICH PERMISSION IS GRANTED |) | | | _ |
| REPAIR TO TAP | SEWER ON THE | | Halith | , (|
| ofOut | AVE STAYPE OF STREET | • | 1200 plat 1 2 1 - | _ |
| THE PREMISES BEING LOT NO | 16296 | , HOUSE NO | 1228 | |
| WORK TO BE DONE IN ACCORDANCE | · WITH ORDINANCE NO. 19.1971 DULY PA | ASSED BY THE C | SITY COUNCIL AND BULES OF THE | |
| DEPARTMENT OF PUBLIC SERVICE. | / / / / / / / / / / / / / / / / / / / | | · · · · · · · · · · · · · · · · · · · | |
| | $f_{*}=f_{*}=g$ | ** | | |
| NAME OF CONTRACTOR | The deve | | | |

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.