

N^o 11407

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12/12/01

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

15'

HOUSE NO. 1015

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Steve Miller Exc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

[Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11407

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/11/01, 2001

RECEIVED OF _____ FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED Steve Miller Excavating

REPAIR TO TAP tap existing SEWER ON THE West S
CUTOFF

OF Lansdale Street NW AVE.
ST. TYPE OF STREET asphalt

THE PREMISES BEING LOT NO. 16000, HOUSE NO. 1015

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Steve Miller Excavating

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.