FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	12/1901	IF SO, HOW AND LOCATION FROM 90' FIRST MANHOLE DOWN STREAM		
HOUSE NO.	2119			
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT		
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH		
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTORBuckeye Wrecking		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
		2119 Lincoln Way East 93' behind curb		
·				
	,	G 80, carp		
SIGNED JAH M	Inspector for City	FILED AT ENGINEER'S OFFICE		

Nº 11408

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,				
RECEIVED OF		FEE OF \$			
FOR WHICH PERMISSION IS GRANTED	Buckeye Wrec	King Bucker & war P			
REPAIR TO TAP CUITOFF	/ SEWER ON THE	south .			
of Lucala Way Each					
· · · · · · · · · · · · · · · · · · ·		SE NO			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE					
DEPARTMENT OF PUBLIC SERVICE.					
NAME OF CONTRACTOR	eve				

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.