


N^o 11411

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 1/15/02 IF SO, HOW AND LOCATION FROM 68'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1016
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Cottrill Wrecking
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED *[Signature]* Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11411

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 01/15/02, 2002

RECEIVED OF _____ FEE OF \$ 1

FOR WHICH PERMISSION IS GRANTED Cottrell Wrecking Co. Inc.

REPAIR
TO TAP Cottrell sanitary SEWER ON THE East S
CUTOFF

OF 4th Street SW AVE. asphalt
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 4126, HOUSE NO. 1011

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Cottrell

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**