## $N^{\circ}$ $1\overline{1}4\overline{1}\overline{2}$

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	1/18/02	_ IF SO, HOW AND LOCATION FROM	200'		
HOUSE NO.	1343	FIRST MANHOLE DOWN STREAM			
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT			
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH			
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Cottrill Wrecking		
SHOW BY DIAGRAM RELATION	OF LATERAL TO WALL OF	BUILDING SERVED.			
			6'dp, cut-off 48' behind curb		
			1343 16th st se		
			Curb 200' /		
·		D/S MH			
SIGNED Bill Pa	DD 4 S. Inspector for City	FILED AT ENGINEER'S OFF	CE		
	•				
PEMARKS					

## Nº 11412

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

1/18/02			200'	alleton	
1343		MASSILLON, O	HIO,	<u> UITI2/UX</u>	20
RECEIVED 6		:		FEE OF \$	
yes FOR WHICH PERMISSION IS GRANTED	СоН	all we	Cottes W		
	. /		Cottrill Wr	recķing	
REPAIR yes	<u>Scholory</u> sewe	ER ON THE	1.35	74.4	ξ
CUTOFF  OF	AVE. ST. TYPE	E OF STREET	<i>1</i> 3.3	6'dp/ cut-off	
•				48' behind	curb
THE PREMISES BEING LOT NO. $10^{L}$	103 Ct	<u>, i</u>	HOUSE NO	143	
			1343 16th st s	• /	_
WORK TO BE DONE IN ACCORDANCE V	WITH ORDINANCE NO. 19	1971 DULY PASSE	D BY THE CITY CO	200* / DUNCIL AND BULES OF I	THE
	(	)			.,
DEPARTMENT OF PUBLIC SERVICE.	Call ill	MH			
NAME OF CONTRACTOR	<u> </u>				

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.