

N^o 11413

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1/15/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

105'

HOUSE NO. 2183

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR H&W

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Jeffrey M. King

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11413

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1-15-20

RECEIVED OF A & W FEE OF \$

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP Sanitary SEWER ON THE West S
CUTOFF University

OF University AVE.
ST. TYPE OF STREET West

THE PREMISES BEING LOT NO. 399, HOUSE NO. 243

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A & W for Telling

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**