

Nº 11414

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 1/15/02

HOUSE NO. 2187

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 105'

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

NAME OF CONTRACTOR H&W

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11414

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1-15

RECEIVED OF H & W

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP _____
CUTOFF _____

SEWER ON THE _____

OF _____

AVE.
ST. TYPE OF STREET _____

THE PREMISES BEING LOT NO. _____

HOUSE NO. 2187

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H & W

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**