

N^o 11416

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1/22/02

HOUSE NO. 1636

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 59'

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

NAME OF CONTRACTOR Shear

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 11416

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1-18, 20
RECEIVED OF Robert Schaefer FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP Lebanon SEWER ON THE Lebanon S
CUTOFF

OF Charles H. Lane AVE. ST. TYPE OF STREET Lebanon

THE PREMISES BEING LOT NO. PT. 06.208, HOUSE NO. 1636

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Shaw

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**