


Nº 11417

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1/24/02 IF SO, HOW AND LOCATION FROM 267'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1854
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Kevin Glick
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Jeffrey M. King FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11417

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1-22, 2022
RECEIVED OF Henry Glick FEE OF \$ 1.50

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP Sanitary SEWER ON THE North S
CUTOFF Delmont St AVE.
OF Delmont St ST. TYPE OF STREET Delmont St

THE PREMISES BEING LOT NO. 6180, HOUSE NO. 1857

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Glick

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**