


Nº 11418

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1/22/02 IF SO, HOW AND LOCATION FROM 55'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 1390
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Malavite
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature] FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11418

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____

1-20

RECEIVED OF _____

Massillon

FEE OF \$ _____

52

FOR WHICH PERMISSION IS GRANTED _____

REPAIR
TO TAP
CUTOFF

South

SEWER ON THE _____

South

S

OF _____

Armed

AVE.

ST. TYPE OF STREET _____

Armed

THE PREMISES BEING LOT NO. _____

16052

, HOUSE NO. _____

1390

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Sign Taylor

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**