


Nº 11419

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3/11/02 IF SO, HOW AND LOCATION FROM 295'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 2420
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Bontrager
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pappas FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 11419

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 1-24
20

RECEIVED OF Bontlinger

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED

REPAIR
TO TAP
CUTOFF

SEWER ON THE North

S

OF Urban Ave

AVE.

ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 16239

HOUSE NO. 2420

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Efficient Homes

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**