N^{0} 11425

REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	2/4/02	IF SO, HOW AND LOCATION FROM		5'		
HOUSE NO.	1212	FIRST MANHOLE DC	JWN STHEAM			
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT				
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH				
WAS ATTACHED TO MAIN	yes	. NAME OF CONTRAC		ottrill		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.						
			1212 Cleveland ST SW			
•		6'dp T cul-off				
			5 3,5	55' behind curb		
			Cleveland ST SW	Curb		
		O				
SIGNED Bill Pap	PqS Inspector for City	F	ILED AT ENGINEER'S OFFICE			

Nº 11425

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	Cathui	MASSILLON, OHIO,	2 / 1 , 20
OR WHICH PERMISSION IS GRAN	TED		A
REPAIR O TAP	Landa Man SEWER	ONTHE TO BE A SECTION OF A	last
CUTOFF CLU		OF STREET AS	
HE PREMISES BEING LOT NO			1212
ORK TO BE DONE IN ACCORDAN	CE WITH ORDINANCE NO. 19.19	71 DULY PASSED BY THE CITY COL	JNCIL, AND RULES OF THE
EPARTMENT OF PUBLIC SERVICE			
AME OF CONTRACTOR	Latlie	el.	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.