## Nº 11426

REMARKS \_\_\_\_\_

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	2/4/02	IF SO, HOW AND LOCATION FROM	113'
HOUSE NO.	4580-4582	FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	yes ·		AND AND THE PARTY OF THE PARTY
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Glick
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
		. ;	4580 3 dp 4582
			29'
			50'
	0	113'	12'dp
SIGNED BIT Papp	0a5	FILED AT ENGINEER'S	OFFICE
• •	Inspector for City		

Nº 11426

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/, 20_  RECEIVED OF SEE OF \$ 5
FOR WHICH PERMISSION IS GRANTED
TO TAP CUTOFF  CUTOFF  CHANGE (LE PHYPE OF STREET ASMALL)
THE PREMISES BEING LOT NO. $\frac{0}{16159}$ , HOUSE NO. $\frac{0}{180-45}$
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.