

Nº 11427

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 2/07/02

IF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

105'

HOUSE NO. 310

SIZE OF PIPE USED X" 4"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR H&W

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED [Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE

Home Owner was advised that city codes require residential sanitary service laterals to be 6in. Because of cost, Homeowner elected to stay with 4in service

REMARKS

Nº 11427

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

RECEIVED OF H+W MASSILLON, OHIO, 2/6, 2050

FOR WHICH PERMISSION IS GRANTED Walnut

REPAIR
TO TAP
CUTORE

SEWER ON THE North

OF Walnut

AVE.

ST. TYPE OF STREET Asphalt

THE PREMISES BEING LOT NO. 3031

, HOUSE NO. 30310

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H+W

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**