


N^o 11428FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNEDDATE INSPECTED 2/8/02HOUSE NO. 344SIZE OF PIPE USED 6"WAS LATERAL AT CURB? yesWAS ATTACHED TO MAIN yesIF SO, HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 115'DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____NAME OF CONTRACTOR Pachan Construction

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED *[Signature]* FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

Nº 11428

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/7/2002

RECEIVED OF _____ FEE OF \$ _____

FOR WHICH PERMISSION IS GRANTED Pachan Construction

REPAIR TO TAP tap sanitary SEWER ON THE North S
CUTOFF

OF Shaw Ave NE AVE. asphalt
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 15883, HOUSE NO. 344

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Pachan Construction

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.