


N^o 11433

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2/13/02 IF SO, HOW AND LOCATION FROM 277'
FIRST MANHOLE DOWN STREAM
HOUSE NO. 126
SIZE OF PIPE USED 6" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? yes
WAS ATTACHED TO MAIN yes NAME OF CONTRACTOR Dickerson
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

[Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 11433

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/13, 2021
RECEIVED OF Deckerason Contracting FEE OF \$ 271

FOR WHICH PERMISSION IS GRANTED _____

REPAIR Sanitary SEWER ON THE North S
TO TAP CUTOFF
OF Wright Ave AVE. ST. TYPE OF STREET Asphalt
THE PREMISES BEING LOT NO. 2382, HOUSE NO. 126

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deckerason

**Note: This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health regulations.**